

## Revise History

Date	Version	Revision
8/5/2022	1.08.01.15R2	<ol style="list-style-type: none"> <li>Fixed the bug that startup occasional failures</li> <li>Fixed the bug of burst sync output exception</li> <li>Fixed the bug that may not output when switch the waveform after the burst is turn off</li> </ol>
12/3/2020	1.08.01.15	<ol style="list-style-type: none"> <li>Supported to automatically enable the output after power-on: Utility   Output Setup   Power on State</li> <li>Compatible with Rev.E hardware</li> </ol>
7/16/2019	1.08.01.13R9	Fixed the abnormal display issue during start-up on some units with previous releases. It is not necessary to update to this version if the unit has no such a problem.
8/30/2018	1.08.01.13R6	Fixed the incorrect sweep direction bug (2018/05/23-115276)
3/21/2018	1.08.01.13R5	<p><b>It is strongly recommended to update to the latest release because in some previous release exists some serious bug which could cause the generator never startup</b></p> <ol style="list-style-type: none"> <li>Supported system recovery from the U-disk</li> <li>Supported Rev.C hardware with Over Voltage Protection</li> </ol>
6/7/2016	1.08.01.12R2	Fixed several bugs <ol style="list-style-type: none"> <li>A bug in P12R1 which could cause the update to fail</li> <li>Some typo in English help system</li> </ol>
3/7/2016	1.08.01.12R1	Fixed several bugs <ol style="list-style-type: none"> <li>A bug in file system could cause the generator never startup</li> <li>Can not wake up from screen saver from time to time</li> </ol>
11/9/2015	1.08.01.11	<ol style="list-style-type: none"> <li>Re-open the self-calibration function</li> <li>Fixed a bug which may cause the generator can not startup</li> <li>Fixed several other bugs</li> </ol>